Lessons Learned: Hazard Identification-Unsafe work



Nature of Incident	Classification of Incident	Location of Incident
Hazard Identification-unsafe	Incident-Hazard Identification	Lethbridge School Division

Brief Description of Incident

On February 19, 2020 at approximately 3:00 PM a school staff observed a contractor staff in one of laundry rooms, working on a ladder in a ceiling, with the ladder placed on a washer & dryer, in the laundry room.

Photograph of Incident



What Went Well?

- ♦ Staff took a picture of the incident and sent the picture to the supervisor and maintenance
- ♦ There were no injuries.
- ♦ Maintenance and OH&S met with owners of the con- ♦ Staff member did not stop worker from unsafe tracting company in question
- ♦ A lessons Learned was developed to reduce risk of future incidents

What Went Wrong?

- ♦ Failure to follow procedure/policy
- ♦ Hazard not recognized
- Job safety training not followed
- work
- Incident was reported two days after it occurred

System Causes

- ♦ Job / Safety Training not followed
- ♦ Sufficient job safety planning not conducted Hazard assessment.
- Hazard not recognized
- Contractor orientation not implemented
- ♦ Hazard not reported immediately
- Stop work protocol not applied

Corrective / Preventative Actions

- **♦ Contractor orientation completed and signed for** all contractors
- **♦ Complete a Hazard assessment before work task** begins.
- **♦ Safety inspections of work area by supervisor.**
- **⋄** Reinforce staff to report incidents immediately and stop unsafe work when necessary